Application/Control Number: 10/597,043 Page 2

Art Unit: 2611

DETAILED ACTION

1. It would be of great assistance to the Office if all incoming papers pertaining to a filed application carried the following items:

- 1. Application number (checked for accuracy, including series code and serial no.).
- 2. Group art unit number (copied from most recent Office communication).
- 3. Filing date.
- 4. Name of the examiner who prepared the most recent Office action.
- 5. Title of invention.
- 6. Confirmation number (See MPEP § 503).

Specification

2. The substitute specification filed 9/25/09 has not been entered because it does not conform to 37 CFR 1.125(b) and (c) because: a) the statement as to a lack of new matter under 37 CFR 1.125(b) is missing and b) a clean copy of the substitute specification has not been supplied (in addition to the marked up copy).

Drawing

3. The drawings are objected to as failing to comply with 37 CFR 1.84(p) (4) because reference character "11clk1, 12ckl2 etc" has been used to designate both fig.2A and fig 6 and further more figs.1 and 5 and 2A and 6 are the same. Corrected drawing sheets in compliance with 37 CFR 1.121(d) are required in reply to the Office action to avoid abandonment of the application. Any amended replacement drawing sheet should include all of the figures appearing on the immediate prior version of the sheet, even if only one figure is being amended. Each drawing sheet submitted after the filing date of an application must be labeled in the top margin as either "Replacement Sheet" or "New Sheet" pursuant to 37 CFR 1.121(d). If the changes are not accepted by the examiner, the applicant will be notified and informed of any required

corrective action in the next Office action. The objection to the drawings will not be held in abeyance.

Conclusion

Any inquiry concerning this communication or earlier communications from the examiner should be directed to Temesghen Ghebretinsae whose telephone number is 571-272-3017. The examiner can normally be reached on Monday-Friday 8:30 a.m. to 6:00 p.m..

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Ghayour Mohammed can be reached on 571-272-3021. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free). If you would like assistance from a USPTO Customer Service Representative or access to the automated information system, call 800-786-9199 (IN USA OR CANADA) or 571-272-1000.

Temesghen Ghebretinsae Primary Examiner Art Unit 2611 Application/Control Number: 10/597,043 Page 4

Art Unit: 2611

Primary Examiner, Art Unit 2611

12/17/09